



GREG BELL Lieutenant Governor

State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA

Division Director

Representatives Present During the Inspection: OGM Pete Hess

Inspection Report

Permit Number:	C0070016
Inspection Type:	COMPLETE
Inspection Date:	Wednesday, September 07, 2011
Start Date/Time:	9/7/2011 9:00:00 AM
End Date/Time:	9/7/2011 11:50:00 AM
Last Inspection:	Wednesday, September 07, 2011

Inspector: Pete Hess,

Weather: Clear and cool; 70's F. InspectionID Report Number: 2856

> Accepted by: jhelfric 9/14/2011

Permitee: CANYON FUEL COMPANY Operator: CANYON FUEL COMPANY

Site: GORDON CREEK 2, 7 & 8 MINES Address: HC 35 BOX 380, HELPER UT 84526

County: CARBON

Permit Type: PERMANENT COAL PROGRAM

Permit Status: RECLAIMED

Current Acreages

Total Permitted	179.27
Total Disturbed	34.15
Phase I	32.52
Phase II	32.52
Phase III	0.73

Mineral Ownership

Types of Operations ✓ Federal ✓ Underground State Surface County Loadout Processing Other Reprocessing

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The status of the site remains unchanged.

Inspector's Signature:

Date Wednesday, Sept



Pete Hess,

Inspector ID Number: 46

Permit Number: C0070016 Inspection Type: COMPLETE

Inspection Date: Wednesday, September 07, 2011

Page 2 of 4

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	✓		✓	
2.	Signs and Markers	~			
3.	Topsoil		✓		
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments	✓		✓	
4.c	Hydrologic Balance: Other Sediment Control Measures		✓		
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations	✓		✓	
5.	Explosives		Y		
6.	Disposal of Excess Spoil, Fills, Benches		V		
7.	Coal Mine Waste, Refuse Piles, Impoundments		~		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓		✓	
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading	✓		~	
13.	Revegetation	✓		~	
14.	Subsidence Control		✓		
15.	Cessation of Operations		✓		
16.8	a Roads: Construction, Maintenance, Surfacing		✓		
	o Roads: Drainage Controls		✓		
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations		✓		
19.	AVS Check	✓			
20.	Air Quality Permit		✓		
21.		V		V	
22.	Other	✓		✓	

Permit Number: C0070016 Inspection Type: COMPLETE

Inspection Date: Wednesday, September 07, 2011

Page 3 of 4

1. Permits, Change, Transfer, Renewal, Sale

The current DOGM permit was re-newed on August 28, 2009; the only Special Condition which exists relative to this permit is to submit required quarterly water data to the Division electronic data base in an electronic form. The Permittee continues to meet this requirement.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The third quarter 2011 impoundment inspection for the Jacob's Pond stock watering impoundment was conducted by Ms. Vicki Miller on August 30, 2011. The pond was observed as stable, with no hazards identified. As observed this day, the pond is approximately three-fourths full, and is not discharging. There were no fresh tracks about the waterline, and the water was turbid.

4.d Hydrologic Balance: Water Monitoring

There was no flow observed either in Bryner Creek or in any of the reclaimed lateral diversions. The Permittee notified the Division on March 31, 2011 that the fourth quarter 2010 water monitoring data for the Gordon Creek 2 / 7/8 permit area had been successfully uploaded into the DOGM permanent data base.

4.e Hydrologic Balance: Effluent Limitations

There are no permitted UPDES outfalls at this location. The Permittee notified the Utah Division of Water Quality on November 21, 2007 that the reclamation of the three cell sediment pond (and the point source outfall) had been completed. A discharge monitoring report for November 2007 was submitted, but reported as no flow. No DMR's have been submitted since that date.

9. Protection of Fish, Wildlife and Related Environmental Issues

No wildlife was observed during today's inspection. The Permittee sprayed the reclamation site for Musk Thistle in July and August, 2011.

12. Backfilling And Grading

All backfilled areas appear to be in a stable condition.

13. Revegetation

The re-vegetated reclamation area is beginning to turn brown. Musk thistle plants were treated with herbicide in July and August, and many have died.

21. Bonding and Insurance

The Permittee re-newed the required general liability insurance coverage prior to July 31, 2011. Current coverage remains in effect through July 31, 2012. Coverage for damage incurred from the use of explosives is provided. Coverage limits for general aggregate and each occurrence categories meet the requirements of R645-301-890.100. The amount of reclamation bond posted for this site is \$ 641,443.00.

Permit Number: C0070016 Inspection Continuation Sheet

Inspection Type: COMPLETE

Inspection Date: Wednesday, September 07, 2011

Page 4 of 4

22. Other

At the request of the land-owner, the Permittee has installed a new gate 40 feet east of the access road terminus. The location is off the permit area, yet remains on Jacob's land.